

INDUSTRIAL RELATIONS
741.5

Review Committee File No. 833
Coast Valleys Division Grievance No. D.Gr/C 18-68-8
Job Definition and Duties of a Mechanic

RECEIVED
MAR 24 1969
LOCAL 1245, I.B.E.W

March 20, 1969

MR. E. E. HYDE, Chairman
Coast Valleys Division
Joint Grievance Committee

The above-subject grievance has been discussed at meetings of the Review Committee. It is the decision of the Review Committee that in this instance the work assignment performed by the grievant is within the agreed-to job definition of a Mechanic.

From a review of the facts and additional information provided by the Division, it has been determined that the work performed by the grievant was not done to provide a steam or water-tight seal. The nipple was tack welded in place and expanded for the purpose of facilitating the welding of the nipple in the manifold. After the nipple was expanded sufficiently the Welder ran a bead completely around the nipple and the edge of the hole which provided the necessary seal.

This case is considered closed and should be so noted in the minutes of your next Joint Grievance Committee meeting.

L. V. BROWN

L. V. BROWN, Chairman
Review Committee

PNLong:RS

cc: LHSmith
TJBianucci
CRMachen
IWBonbright
RRJames
JJWilder, IBEW