

SAFETY ALERT

TARGET AUDIENCE: ALL EMPLOYEES | **COMMUNICATION:** 24 HOURS

Utility Vehicles from Two Different Manufacturers Recalled

Utility vehicles from two different manufacturers have been recalled due to a faulty rear brake line. Polaris and Bobcat have recalled about 1,640 vehicles because the rear brake line can become punctured, causing a brake failure which creates a collision and crash hazard. Polaris has received nine reports of rear brake failures. Bobcat has not received any reports at this time. Neither manufacturer have received reports of injuries, according to U.S. Consumer Product Safety Commission recall number 20-715, 20-714, and 20-713.

The recall affects the Polaris Brutus DSL HD PTO and Brutus DSL HD PTO DLX in the 2017 and 2018 model years. Polaris PRO XD in the two and four-seat configurations in the 2019 model year, and the Bobcat 3650 in the 2017 and 2018 model years.

The Polaris Brutus vehicles were sold at dealers between May 2016 and April 2019. The Polaris PRO XD between November 2017 and November 2019. The Bobcat vehicles were sold at dealers between May 2016 and February 2019.

In all cases, facility managers with the recalled vehicles in their fleet are directed to remove them from use and contact a Polaris or Bobcat dealer for a free inspection and repair. To find out if a Polaris vehicle is part of a safety recall, visit the Polaris website or call 800-765-2747. Bobcat vehicle recalls can be found by visiting the Bobcat website or call 800-743-4340.



1,640 vehicles recalled due to rear brake line becoming punctured, causing brake failure.